



2600 Bull Street Columbia, SC 29201-1708

COMMISSIONER: C. Earl Hunter

BOARD: Bradford W. Wyche Chairman

Mark B. Kent Vice Chairman

Howard L. Brilliant, MD Secretary

Carl L. Brazell

Louisiana W. Wright

L. Michael Blackmon

Larry R. Chewning, Jr., DMD

Commander NAVFACENGCOM Southern Division Attn: Code ES24 (Gabriel Magwood) P.O. Box 190010 North Charleston, SC 29419-9010

Re: CNB – Zone H, Site 44 (AST 601)

Site Identification # 01537

Remediation Monitoring Report received 16 January 2003

Charleston County

Dear Mr. Magwood:

The Department has completed technical review of the referenced document. As submitted, the Remediation Monitoring Report provides an outline of active corrective action activities conducted to remediate hydrocarbon contamination at the referenced facility.

Soil contamination in excess of established RBSL limits was defined and excavated per the CAP. Groundwater sampling activities indicted the presence of free phase petroleum in monitoring wells CNC44MW01 & CNC44MW04. The Department concurs with the recommendation of your contractor that free product continue to be removed from the affected monitoring wells and, once free product has been removed, establish a monitoring program. Please note that the Department retains the right to require additional monitoring points at the conclusion of remediation activities to verify remediation goals.

Please provide the Department with a free product removal report on a quarterly basis. The Department should receive the next product removal report no later than 28 March 2003. Should you have any questions please contact me at 803-898-3553 (office phone), 803-898-2893 (fax) or by e-mail bishopma@dhec.sc.gov.

Sincerely,

Michael A. Bishop, Hydrogeologist Groundwater Quality Section

Bureau of Water

cc:

Trident District EOC

Jerry Stamps, SCHDEC-BLWM

Brian Crawford, 1849 Ave. F, N. Charleston SC, 29405

Technical File